Oil Field Environmental Incident Summary

Incident: 20140730101411 Date/Time of Notice: 07/30/2014 10:14 Responsible Party: STATOIL OIL & GAS LP Well Operator: STATOIL OIL & GAS LP Well Name: LLOYD 34-3 2H Field Name: SANDROCKS Well File #: 21033 Date Incident: 7/28/2014 Time Incident: 15:00 Facility ID Number: **MCKENZIE** *Twp:* 151 Rna: 100 Sec: 34 Qtr: County: Location Description: Submitted By: Jake Way Received By: Contact Person: Jake Way 6300 BRIDGE POINT PKY, BLDG 2 SUITE 500 AUSTIN, TX 78730 General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil Distance Nearest Occupied Building: 1 Mile 1 Mile Distance Nearest Water Well: Type of Incident: Pipeline Leak Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No Spilled Units Recovered Units **Followup Units** Oil Brine 2 **Barrels Barrels** 2 Other **Description of Other Released Contaminant:** Inspected: Written Report Received: Clean Up Concluded: Risk Evaluation: None

Areal Extent:

Potential Environmental Impacts:

Affected soil on well site location

Action Taken or Planned:

Affected soil will be properly disposed of and connection repaired.

Wastes Disposal Location: PDI

Agencies Involved:

Updates

Date: 7/31/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an on-location pipeline leak, remained on location, within the diking, according to the report. NDIC retains oversight.